REGISTERED ACCESSIBILITY SPECIALIST BULLETIN



Texas Department of Licensing and Regulation • Compliance Division • Architectural Barriers

Owner Response Requirement

RAS 2023-06

Effective Date: September 1, 2023

Rule Reference: 68.40(d)

The intent of Texas Administrative Code Chapter 68.40(d) is for the owner to provide a written response to the RAS or department through the prescribed TDLR Inspection Response Form (EAB-229N) no later than 30 days of the date of the inspection report. The owner, through the form, indicates to the RAS or the department the completion of corrections to cited violations, a request for extension of time to correct the cited violations, or that an application for a variance will be submitted. Where corrections will be made after an extension or variance request is submitted, all information requested in the applicable field must be provided.