



TEXAS DEPARTMENT OF LICENSING & REGULATION

Executive Office • PO Box 12157 • Austin, Texas 78711 • (512) 463-3173 • Fax (512) 475-2874

www.tdlr.texas.gov

BOILER TECHNICAL GRAM

Number: 2023-01

Date: March 21, 2023

To: Authorized Inspection Agencies
Texas In-Service Commissioned Boiler Inspectors

From: **Office of the Executive Director**
Office of the Chief Boiler Inspector, Regulatory Program Management
Division

Subject: Inspection of Power Miniature Boilers Integrally Installed in a Steam Sterilizer

References: - Texas Boiler Law, Health and Safety Code Ch. 755, Sec. 755.025 Inspection
- Texas Administrative Code, Ch 65, Sec. 65.208(a) Minimum Clearances

All steam sterilizers with integrated power miniature boilers, installed per manufacturer recommendations, should be inspected according to manufacturer recommendations and current department laws and rules specified above as references. A borescope can be used to conduct the inspection.

If the device is installed as recommended by the manufacturer and no other issues are found, a certificate should be issued.

Questions regarding this Technical Gram should be addressed to the Executive Director and Chief Boiler Inspector.

Mike Arismendez
Executive Director

Rob Troutt
Chief Boiler Inspector